

Simpson Gumpertz & Heger Inc. Consulting Engineers

27 March 2006

Boston Los Angeles New York San Francisco Washington, DC

Yi-Tso Jeff Chen, AIA McGinnis Chen Associates Inc 10 Nottingham Place San Francisco, CA 94133

Project 060230 – Spandrel Glass Surface Stress Measurements, 250 N Street, Sacramento. CA

Dear Mr. Chen

As you requested I visited the above named site with Tammy Siliznoff (SGH San Francisco) on 25 March and met with you and Jeff Martin. We measured the residual surface compressive stress (RSCS) on a number of lites of spandrel glass and on samples provided by you.

We measured the RSCS in accordance with the methods described by ASTM C1279 using a grazing angle surface polarimeter (laser GASP by Strainoptic Technologies). On each lite we measured, we made two measurements, vertical and horizontal. We initially attempted to measure the RSCS on the frit (inside surface) of the spandrel glass by removing the frit with a disc sander. We were unable to get readings on the frit side of the glass, including attempts on the samples you provided. We determined that the outside surface of the spandrel glass is the tin side using an ultraviolet lamp. We measured the surface RSCS in the outside surface of the three samples you provided, 20 spandrel glass panels on the building, and in a broken shard of spandrel glass that we found in the parking lot. The following table lists our findings.

| Test No. | Elevation | Floor | Window number (from left end of elev. As viewed from outside) | RSCS (psi) Horizontal | RSCS (psi) Vertical |
|-------------|-----------------------------|-------|---|--------------------------|------------------------|
| Α | Shards provided by Mr. Chen | | Sample 1 | 9364 | 8685 |
| В | | | Sample 4 | 8370 | 8370 |
| U | | | Sample 5 | 10970 | 10970 |
| 1 | South | 4 | 2 | nr | nr |
| 2 | South | 4 | 11 | nr | nr |
| 3 | South | 23 | 22 | 9364 | 9015 |
| 4 | South | 23 | 16 | 7783 | 7509 |
| 5 | South | 23 | 7 | 10533 | 9732 |
| 6 | North | 23 | 22 | 9364 | 9732 |
| 7 | North | 23 | 16 | 9364 | 9732 |
| 8 | North | 23 | 6 | 9015 | 9364 |
| 9 | West | 23 | 17 | 9732 | 9732 |
| 10 | West | 23 | 13 | 10120 | 10120 |
| 11 | West | 23 | 7 | 9732 | 10120 |
| 12 | East | 23 | 9 | 9732 | 9364 |

| Test No. | Elevation | Floor | Window number (from left end of elev. As viewed from outside) | RSCS (psi) Horizontal | RSCS (psi) Vertical |
|-------------|-----------|-------|---|--------------------------|------------------------|
| 13 | East | 23 | 14 | 9732 | 9364 |
| 14 | East | 23 | 19 | 8685 | 9364 |
| 15 | West | 3 | 3 from door | 9364 | 9015 |
| 16 | West | 3 | 6 from door | 9364 | 9732 |
| 17 | West | 3 | 8 from door | 10120 | 10533 |
| 18 | West | 3 | 10 from door | 9015 | 9732 |
| 19 | South | 3 | 2 | 8370 | 9364 |
| 20 | South | 3 | 4 | 10533 | 9732 |
| 21 | South | 3 | Shard found in lot | 10970 | 10970 |
| 22 | South | 3 | 15 | 9364 | 8685 |
| 23 | South | 3 | 23 | 8370 | 9364 |

nr - No reading, attempted to read the frit side of the glass.

All of the glass we measured including 20 spandrel lites on the building, 3 samples provided by you, and a shard found in the parking lot have RSCS in the range of 7,509 psi to 10,533 psi. We did not measure any glass with RSCS indicating annealed glass.

Sincerely yours,

Arthur G. Davies Jr., Sr. Staff Engineer O:\DATEFILE\2006\Davies\AGD15-R-mgg.doc

cc: Thomas A. Schwartz